

## **M/s Garg Construction & Co, Haldiya**

- i. The camp is located with human settlement adjoining the camp.
- ii. The “No Objection Certificate / Consent” issued for the plant has expired on December 2006. This needs to be renewed from Punjab Pollution Control Board.
- iii. It was advised that Information Kiosk should be in place before start of construction work.
- iv. Drain from water tank near submersible pump need to be made *pucca* with draining of waste water to soak pit.
- v. Fire safety measures near oil storage, kitchen area are lacking, hence fire safety measures should be provided to these location and other fire accident prone areas.
- vi. The switch board of submersible pump needs to be provided with insulated box to prevent any kind of mishap and properly fitted on wall.
- vii. There was no circulation in the labour quarters, so it was advised to provide circulation in all the rooms.
- viii. Oil soaked soil should be properly stripped and disposed off. The disposal location should be duly approved.
- ix. The soil in the backside of office is loose and erosion prevention measures should be taken up with landscaping.
- x. The waste bitumen drums are not stacked properly. These drums may be stored appropriately in the empty store rooms in front of office.
- xi. Dust is generated in the camp, regular watering should be done to minimize the dust generation.
- xii. Waste water from the bathroom should not be disposed off directly on road instead this should be drained into a soakage pit.
- xiii. It was advised that proper traffic management and safety measures should be taken up during construction bitumen laying process.
- xiv. Waste bitumen mix in the camp can also be utilized for footpath in labour quarter area, which at present is dusty and will turn muddy during rains.
- xv. Advised air and noise quality monitoring. Executive engineer should submit result afterwards.
- xvi. Informed that borrow area and rehabilitation plan is to be submitted.

Some of the good practices adopted by the agency are:

- i. Well defined area for parking of vehicle.
- ii. Well defined bitumen storage room with concrete platform and shed.
- iii. Have proper sanitation facility.
- iv. The bitumen and LDO storage tank are constructed with bricked paved platform all around.