

Inspection of construction camp M/s D S Builders located at Badbar, M/s Garg Construction & Co, located at Haldiya and M/s Singla Construction Co at Ramgarh coming under Sangrur division was made on 12<sup>th</sup> June 2007. During the inspection observations made are listed below:

#### **D S Builders**

- i. The earth used for berm preparation is not being taken from the location of borrow area as submitted (Memo No. 2220, dated 13-11-06) earlier. The earth has been taken from two locations as mentioned in Monthly Progress Report submitted, but details of these two borrow areas locations were not submitted to this office nor Junior Engineer (site in charge) know about this.
- ii. In Longowal town there are long road stretches where berm preparation is yet to be started.
- iii. The cleaning of earth from water bodies at km 13.000 has not started. It was further informed by JE that earth waste at culver work was utilized by local people during field preparation for crop plantation and not by contractor.
- iv. Platform prepared for collection of sludge was dismantled and is dumping off in the camp. It has resulted in generation of heavy dust and contamination of soil by bitumen spillage.