

Inspection of proposed Construction Camp site identified by agency M/s GPL – Brahmaputra (Joint venture) at Chunni on Chandigarh - Sirhind Road was made on 24th March, 2007. During the inspection, some of the recommendations given to the agency are listed below:

1. Top soil should be stripped upto a depth of 10-15 cm and stacked properly in the camp with a maximum height of 2 m. The stack should be turfed to protect it from erosion.
2. The approach road to the camp should be developed properly.
3. During approach road construction, preservation of trees growing along the approach road shall also be taken into account.
4. The camp should be bordered suitably all along the camp location.
5. Considering the proposed layout plan prepared by agency, Respirable Particulate Matter and Respirable Suspended Particulate Matter in air will be high due to location of aggregate stacking in wind direction. It is recommended that the location of site office and aggregate stacking area be reconsidered.
6. It was advised that there should be defined area for labour quarter including with required minimum basic amenities.
7. There are chances of storm water entering camp site from adjoining high land area, so proper drainage measures should be taken up.
8. Aggregate stacking area should be provided with concrete platform with suitable drainage provision.
9. Traffic Management Plan in camp site should be designed in a properly manner to minimize compaction of soil.
10. It was advised to identify waste disposal site and got approved.
11. The proposed layout plan should be prepared considering all activities during construction stage.
12. Contractor was advised to initiate the process of getting the “No Objection Certificate” from Pollution Control Board.